


INSPECTION REPORT

- 1. Date of Inspection : 13/09/2021
- 2. Name of the Scheme : Upgradation of 25 No Pachim Amguri Anganawari Centre with boundary wall at Amguri Pt-II
- 3. Location : Amguri Pt-II , Kalbari GP
- 4. Source of Funding & Year : Assam Adarso Gram Yojana 2018-19
- 5. Implementing agency : Construction Committee
- 6. Total approved amount for the scheme : Rs. 5.00 lakh
- 7. Total amount received by the implementing agency : Rs. 1.50 lakh
- 8. Physical progress of work : 50%
- 9. Item wise works done

Item	No of Tara Pump installed
A.Repairing of AWC	Size of AWC: 4.00 mt X 3.00 mt
1. Plastering of brick wall	
2. Roofing	
3. CC floor	
4. Painting	
B. Construction og boundary wall	Length of wall: 100.00 ft , Height: 5.00 ft
1. Brick wall with plastering	

10. Remarks of Inspecting Officer: Self has visited site of the above mentioned scheme taken under AAGY 2018-19 in respect of Amguri PtII village of Abhayapuri(South) LAC. At the time of visit it was found that 70% work of AWC and 30% work of boundary wall has been completed .



 District Development Commissioner
 Bongaigaon

INSPECTION REPORT

- 1. Date of Inspection : 13/09/2021
- 2. Name of the Scheme : Drinking water facility at Amguri Pt-I and Amguri Pt-II village area
- 3. Location : Amguri Pt-I & Pt-II , Kalbari GP
- 4. Source of Funding & Year : Assam Adarso Gram Yojana 2018-19
- 5. Implementing agency : Construction Committee
- 6. Total approved amount for the scheme : Rs. 5.00 lakh
- 7. Total amount received by the implementing agency : Rs. 1.50 lakh
- 8. Physical progress of work : 30%
- 9. Item wise works done

Item	No of Tara Pump installed
1. Installation of Tara Pump with platform	5 Nos

10. Remarks of Inspecting Officer: Self has visited site of the above mentioned scheme taken under AAGY 2018-19 in respect of Amguri PtI village of Abhayapuri(South) LAC. At the time of visit it was found that installation of 5 nos Tara Pump out of 12 nos have been installed at different location. Also construction of platform is going on. Overall 30 % work has been completed and work found satisfactory.



 District Development Commissioner
 Bongaigaon

INSPECTION REPORT

- 1. Date of Inspection : 13/09/2021
- 2. Name of the Scheme : Drinking water facility at Amguri Pt-I and Amguri Pt-II village area
- 3. Location : Amguri Pt-I & Pt-II , Kalbari GP
- 4. Source of Funding & Year : Assam Adarso Gram Yojana 2018-19
- 5. Implementing agency : Construction Committee
- 6. Total approved amount for the scheme : Rs. 5.00 lakh
- 7. Total amount received by the implementing agency : Rs. 1.50 lakh
- 8. Physical progress of work : 30%
- 9. Item wise works done

Item	No of Tara Pump installed
1. Installation of Tara Pump with platform	5 Nos

10. Remarks of Inspecting Officer: Self has visited site of the above mentioned scheme taken under AAGY 2018-19 in respect of Amguri PtI village of Abhayapuri(South) LAC. At the time of visit it was found that installation of 5 nos Tara Pump out of 12 nos have been installed at different location. Also construction of platform is going on. Overall 30 % work has been completed and work found satisfactory.



 District Development Commissioner
 Bongaigaon

INSPECTION REPORT

- 1. Date of Inspection : 13/09/2021
- 2. Name of the Scheme : Construction of Entry Gate at starting point of Amguri Pt-I village.
- 3. Location : Amguri at Kalbari GP
- 4. Source of Funding & Year : Assam Adarso Gram Yojana 2018-19
- 5. Implementing agency : Construction Committee
- 6. Total approved amount for the scheme : Rs. 10.00 lakh
- 7. Total amount received by the implementing agency : Rs. 3.00 lakh
- 8. Physical progress of work : 35%
- 9. Item wise works done

Item	Measurement
1. Earth work. 2. RCC work of foundation, footing, base of columns, Post	Size of gate: Length = 36.00 ft Breadth = 9.00 ft

10. Remarks of Inspecting Officer: Self has visited site of the above mentioned scheme taken under AAGY 2018-19 in respect of Amguri PtI village of Abhayapuri(South) LAC. At the time of visit it was found that construction work of Entry Gate at Amguri Pt-I has been started by the construction committee. RCC work of foundation, footing, base of columns, pile cap, Post have been started and work found satisfactory.


 District Development Commissioner
 Bongaigaon


INSPECTION REPORT

31

1. Date of Inspection : 13/09/2021
2. Name of the Scheme : Upgradation of school building of Amguri Pt-II ME School
3. Location : Amguri Pt-II at Kalbari GP
4. Source of Funding & Year : Assam Adarso Gram Yojana 2018-19
5. Implementing agency : Construction Committee
6. Total approved amount for the scheme : Rs. 10.00 lakh
7. Total amount received by the implementing agency : Rs. 3.00 lakh
8. Physical progress of work : 40%
9. Item wise works done

Item	Measurement
1. Earth work.	Size of bldg: 10.00 mt X 6.00 mt
2. PCC work of foundation, RCC Post	Varandha : 10.00 Mt X 2.00 mt
3. Brick work	
4. Wooden frame of Door & window	

10. Remarks of Inspecting Officer: Self has visited site of the above mentioned scheme taken under AAGY 2018-19 in respect of Amguri PtI village of Abhayapuri(South) LAC. At the time of visit it was found that construction work of school bldg is under progress. Plinth, brick work upto top lintel , fittings of wooden frame of door and windows have been completed so far . Overall 40 % work has been completed and work found satisfactory.


District Development Commissioner
Bongaigaon